

U.S. Government

Federal law prohibits removal of this label before consumer purchase.

# ENERGYGUIDE

Central Air Conditioner  
Cooling Only  
Split System

CENTURY  
Model SAC1330S1A



Efficiency Rating (SEER 2)\*\*

13.40\*



13.4  
Least Efficient

27.0  
Most Efficient

Range of Similar Models

\*\* Seasonal Energy Efficiency Ratio 2

For energy cost info, visit  
[productinfo.energy.gov](http://productinfo.energy.gov)

\* Your air conditioner's efficiency  
rating may be better depending on  
the coil your contractor installs.

## Notice

Federal law allows this unit to be installed **only in:**

AK, CO, CT, ID, IL, IA, IN, KS, MA,  
ME, MI, MN, MO, MT, ND, NE, NH,  
NJ, NY, OH, OR, PA, RI, SD, UT, VT,  
WA, WV, WI, WY, and U.S. territories.



Federal law prohibits installation of this unit in other states.

**Energy Efficiency Ratio 2 (EER2):** The installed system's minimum EER2 is 11.20.